


Converting an Image to Vectors for Laser Cutter

1

Open Illustrator


- ▶ **Select Window Tab on the Menu Bar**
- ▶ **Select Image Trace**
(This brings up the Image Trace bar)



6

Adjust Linework


- ▶ **Set Fill to none**
- ▶ **Set Stroke to black**



2

Image Trace Window


- ▶ This is used to edit the parameters for the image to be traced



3


Import an Image to Illustrator

- ▶ **Select the Image**
- ▶ **Select Object tab on the Menu Bar**
- ▶ **Select Image Trace**
- ▶ **Select Make**





4

Edit Image Trace Settings (see settings pages for details)






5




Expand Trace



Setting 1



Setting 2



Setting 3

